

## Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

☐ RECOMMEND UPDATING ALL UNITS.

☐ UPDATE UNITS S/N: \_\_\_\_\_  
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

☒ NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

---

---

---

---

---

---

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

-added new 3 second press/hold reset feature for protection circuitry. This is an alternative method for resetting protection circuits on amplifiers. This feature has been implemented to accommodate installations where the AC power cord is difficult to access. The original method required that the AC power cord be disconnected and reconnected. The new method is to press and hold the standby button for 3 seconds to reset amplifier protection circuits.

-support has been added to prevent occasional false activation of Communication Error fault reports.