

Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

☐ RECOMMEND UPDATING ALL UNITS.

☐ UPDATE UNITS S/N: _____
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

☒ NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

- Fully CAN-Bus ready with improved IR performance.

NOTE:

- If you have not already updated your amp with the previous 3.0.0 code (available since Dec. 19/06) then you will need to update the amp to the new 3.0.1 code for the amp to be CAN-Bus ready.

- If you have already updated to 3.0.0 and the system does not require the use of an IR jack then this update is not necessary.

- This software release is a stage in the CAN Bus launch process. Details relating to the official CAN-Bus launch will shortly be posted on the Classe website www.classeaudio.com. CAN-Bus will not be fully operational before this point.